

This drawing, specifications, and concepts contained here in are the sole property of Dart Aerospace, and may not be reproduced or used in any fashion without the prior written permission of Dart Aerospace Eugene, OR.

	revisions								
REV	ECR	DESCRIPTION	DATE	INITIAL	APPROVED				
6		CH'D Ø.499 TO Ø.50085005	8/15/2012	JAG					
7		CH'D RADIUS WAS R.015 MAX. IS R.02 MAX. ADDED NOTE 1.		RJC					
7A		CH'D TITLE BLOCK WAS RED BARN IS DART, ADDED BAG & LABEL NOTE, CH'D DIMENSION Ø.625 TO REF., CH'D DIMENSION WAS .350 IS .35.	8/7/2014	DJN	RW				





SECTION A-A

NOTES:

- 1. NICKEL PLATE .0004 .0006, BAKE AFTER PLATING.
- 2. BAG & LABEL WITH BATCH NUMBER.

SEE ATTACHED DEVIATION

									.XX ± .01	AN LL SHARP EDG	GLES ±.5	
ASSY QTY	ASSY QTY	в/О	Part #	UNIT	Description	Material	B/O INFORMATION OR SPECIFICATIONS	PG.	OR .015R			
			C3-12-1	1	LOCK BUSHING	4140	Ø5/8 X 1/2		SCALE	4:1	DATE	11/2/2001

TITLE LOCK BUSHING DWG NO. C3-12-1 7A MAT'L 4140 PRAWN BY: CANAM UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES .XXX ± .001 FRACTIONS ± 1/8 .XX ± .01 ANGLES ± .5° .X ± .1 ANGLES ± .5° .X ± .1 ANGLES ± .5° .X ± .1 SEE NOTE 1 1. BREAK ALL SHARP EDGES .015 x 45° OR .015R USED ON MODEL

SHEET 1 OF 1

DQA:		Date:								
			WORK ORDER NON-C	CONFORMANCE / UPDATE		AEROSPACE				
QA Closed:		Date:			Work Order update only					
Work Order: DISPOSITION			DISPOSITION	AGAINST DEPARTMENT/PROCESS						
Part No.	C3-12-1	1 Rev. 7A	Rework Scrap Use-as-is Suspected Unapproved	Skid-tube Cross tube Machining Small Fab Thermoforming Finishing Large Fab Composite	Prod. Eng. Coor. Rec/Store/Packaging	Quality Other				
Date :		Ste	ep#:	QTY Effective :	Заррнег	MRB (QŞI042) Approval				
						Mee				
	D	escription Work (Order Deviation	Disposition	on	Oct 11, 2018				
	2-1 can be		om 17-4PH-H900 as an	- This deviation is acceptab	Completed By					
		l Nickel plating is r from 17-4PH-H90	not required if the part is 10	- The fit, form and functior as originally intended.	Lead hand / Supervisor Approval Verification					
					QC / QA Coordinator Approval					
	Root Ca	use		FAULT CATEGORY						
Environment		No Re-verfication	Pressure/Forced	Temperature/Cure	Power Loss/Surge	Positioned Wrong				
Design	х	Operator	Bending	Set-up	Folio/Program	Outside Dimensions				
Doc/Data		Offset/Setup	Centre Not Concentric	BOM/Route	Grain	Over/Under tolerance				
Equip/Tooling		Supplier	Cracks	Broken/Damage/Defect	Weld	Part Incorrect				
Handling/Pre		Training	Crimp/Kink/Ripple/Wave	Inspection Incomplete/Unqualified	Wrong Stock Pulled	Part Lost/Missing				
Material	x	Use for Testing	Cuffs	Contamination	Out of Sequence	Part Moved				
Internal Transport		Poor Information	Crushing	Countersink	Off-set	Drawing				
Tribal Knowledge		Rushing	Heat Treat	Cut Too Short	Mislabeled	Finish				
LOA		Product Improvement	Wave/Twist in Tube	Instructions Incomplete/Unclear	Fit/Function	Misread				
Substation		Process Improvement	Marks/Chatter	Drill Holes	Misaligned/off center	Turning Sequence				
Past Expiry Date		Manufacturing Process								
Misidentified		Past Due	OTHER:							